

FIG. 1




FIG.2




FIG.3




FIG.4




FIG.5

CASE OF NO ADJACENT CHANNEL



(a)
NORMAL STATE(b)
DETERIORATION FACTOR: ASE

FIG.6

CASE OF ADJACENT CHANNEL




FIG.7




FIG.8




FIG.9




FIG.10




FIG. 11




FIG.12




FIG.13





FIG.14






FIG.16

